History of Road / Lane / Circle From ..... To .....

Year	Name of Work	Sanctioned Estimate amount and year	Period of Execution	Particulars of the work done	Name of the Contractor	Expenditure booked	J.E. / A.E. incharge	Road cutting done since the work done	Ren should any s feat affect road s
1	2	3	4	5	6	7	8	9	
2015-2016 (1)	Improvement to Road at UBA. Apartment road to Road no.09 of to Road from Venkatadrinagar layout to Gnanashwari layout of Vidyaranyapura [009-11-0000597]	Sub-Division 9.50 Lakhs 2014-15	2015-16	Asphalting to (a) Gnanashwari layout main Road (b) Cross-Road	Charge of Smt. Shanta Kumari	8,81,553/-	Work : Imp in Wood work Suresh AE	—	
2014-15 (2)	Improvements of [009-12-0000021]	Nagappa Circle in Ward No.09. Vidyaranyapura Sub-Division 2012-13 Rs. 37. Lakhs	2012-13 to 2014-15	(1) Asphalting to Nagappa circle (2) Concrete drain and covering slab	B.H. Shivalingam	34,92,046.00	Deviation and Suresh AE	26/06	

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

'Jnaneshwari layout - Main Road' and Nagalpur Circle

(25)

ROAD REGISTER

Road from..... Thadlu - Main - Road ..... To..... 'SWD' ..... Year 20.....

Length or dia of the Circle	Width at every convenient meters	Nature of existing surface	Curb Chainages	FOOT PATH				Particulars of shoulder drains and their Nos. separately for Left & Right sides	Check drains	Existence of service lines Tel. & Cable UGD line WS line etc.	Date of inspection & the initials	R
				Gravel	B.S. Slab	Concrete	Other Surface					
1	2	3	4	5	6	7	8	9	10	11	12	
		Asphalt surface. fully - damaged		–	–	–	–	-	–	W/S and		
1500m	5.0m	(a) Main - Road	→	–	–	-	–	-		UGD Line		
120.0m	5.0m	(b) Cross - Road .	→	–	–	-	–	-			16/01/15	